



ATM SAFETY AND NIGHTIME LIGHTING SURVEY



3530 S. Main St. Salt Lake City, UT (40.7302,-73.63535)

Exterior · Walkup TTW · Diebold Nixdorf Opteva 562







LIGHTING Failed

Reasons:

The illumination at or within five feet of the ATM or ATM entrance is less than 2 foot candles.

The illumination at or within 30 feet of the ATM or ATM entrance is less than 2 foot candles.

The illumination at or within 50 feet of the ATM or ATM entrance is less than 2 foot candles.

Within the parking area the illumination at or within 60 feet of the ATM or ATM entrance is less than 1 foot candles.

Lights Not Working

Item No.	Туре
1	Wall Light

Lights Replacement: None

Reasons Light(s) not replaced Lights Not Replaced as Part of this Survey



SAFETYPassed

Reasons:

Is there a security notice posted near the ATM? **YES**


Is there overgrown landscaping near the ATM or ATM entrance? **YES**


Are mirrors installed on the ATM? Ye **YES**

Are there surveillance cameras monitoring the ATM area? **YES**


First Republic Bank ATM Safety & Lighting Survey

Lighting Diagram





Bank Name ATM Safety & Lighting Survey






45BL TO ATM



45BR TO ATM



45FL TO ATM



45FR TO ATM



45FR TO ATM



ATM TO BEHIND



ATM TO BEHIND



ATM TO FRONT



ATM TO LEFT




ATM TO RIGHT



BACK



BARRIER 30-45BL



BARRIER 30-45BR



BARRIER 30-B



BARRIER 50-R



CARD READER



FASCIA



GENERAL AREA




KEYPAD



LEFT



LIGHT METER ASSET NUMBER



LIGHTING DRAWING DIAGRAM







MONITOR



NON WORKING CANOPY LIGHT




NON WORKING CANOPY LIGHT AREA



RECEIPT



RIGHT



SURVEY MEASUREMENT



Questions?

CONTACT US!

3530 S. Main St., Salt Lake City, UT, 84115 801-975-8860 info@ataservices.com www.ataservices.com

